levelone ®

Quick Installation Guide

|	
English	Português
Deutsch	Svenska
Français	Slovenščina
Español	繁體中文
Nederlands	Русский
Dansk	Polski
Italiano	
Ελληνικά	

CE

CE marking is a certification mark that indicates conformity with health, safety, and environmental protection standards for products sold within the European Economic Area (EEA).The CE marking is also found on products sold outside the EEA that have been manufactured to EEA standards. This makes the CE marking recognizable worldwide even to people who are not familiar with the European Economic Area.

WEEE is waste electrical and electronic equipment. It is end-of-life electrical and electronic equipment and covers virtually everything with a plug or battery. ... The EC introduced the WEEE Directive in 2002 to address the environmental impacts of unwanted electrical and electronic equipment at end-of-life disposal.

Package Content

FGP-1031	x 1
Power Cord	x 1
Manual/QIG	x 1

FGP-1031 10-Port Fast Ethernet PoE Switch, 2 x Uplink Gigabit RJ45, 8 PoE Outputs, 120W PoE Power Budget

Indicator   100M PoE port   1000M Uplink   Function switch

Function Switch

| Mark	Mode	Description
N	Standard Normal	All ports communicate freely,adapting to common data transmission environment
V	Port Isolation	Switch to VLAN mode;downlink isolating from each other,uploads and downloads data through uplink;suppress network failure like broadcast storm and virus attack
S	Super Mode	Downlink speed limitation:10M(Ultral-far transmission:250 meters)

Indicator

Indicator		Status	Description
Power LED:P		Always ON	Normal
		Always OFF	Power Unconnected
		Flashes	Port circuit or cunrrent over-loaded
Port Isolation LED: V		Always ON	Port Isolation mode ON
Super Mode LED: S		Always ON	Super mode ON
PoE LED	Orange	Always ON	Powered equipments connected and power supply narmally
		Always OFF	No powered equipments connected or no power supply
	Green	Always ON	Network signal communicated
		Always OFF	Network signal not communicated

Installation

| Indicator | 100M PoE port | 1000M Uplink | Function switch |

Function Switch

Mark	Mode	Description
N	Standard Normal	All ports communicate freely,adapting to common data transmission environment
V	Port Isolation	Switch to VLAN mode;downlink isolating from each other,uploads and downloads data through uplink;suppress network failure like broadcast storm and virus attack
S	Super Mode	Downlink speed limitation:10M(Ultral-far transmission:250 meters)

Indicator

Indicator		Status	Description
Power LED:P		Always ON	Normal
		Always OFF	Power Unconnected
		Flashes	Port circuit or cunrrent over-loaded
Port Isolation LED: V		Always ON	Port Isolation mode ON
Super Mode LED: S		Always ON	Super mode ON
PoE LED	Orange	Always ON	Powered equipments connected and power supply narmally
		Always OFF	No powered equipments connected or no power supply
	Green	Always ON	Network signal communicated
		Always OFF	Network signal not communicated

Connecting Equipment

Step1. Inspect the Power Adapter carefully, and make

sure that it is properly connected to a power source.

Step2. Plug-in the Power Adapter to the Switch.

Step3. Connect your network devices with the switch

by using Ethernet cable. (e.g. Cat-5e)

Installation

FGP-1031 10-Port Fast Ethernet PoE Switch, 2 x Uplink Gigabit RJ45, 8 PoE Outputs, 120W PoE Power Budget

| Indicator | 100M PoE port | 1000M Uplink | Function switch |

Function Switch

Mark	Mode	Description
N	Standard Normal	All ports communicate freely,adapting to common data transmission environment
V	Port Isolation	Switch to VLAN mode;downlink isolating from each other,uploads and downloads data through uplink;suppress network failure like broadcast storm and virus attack
S	Super Mode	Downlink speed limitation:10M(Ultral-far transmission:250 meters)

Indicator

| Indicator		Status	Description
Power LED:P		Always ON	Normal
		Always OFF	Power Unconnected
		Flashes	Port circuit or cunrrent over-loaded
Port Isolation LED: V		Always ON	Port Isolation mode ON
Super Mode LED: S		Always ON	Super mode ON
PoE LED	Orange	Always ON	Powered equipments connected and power supply narmally
		Always OFF	No powered equipments connected or no power supply
	Green	Always ON	Network signal communicated
		Always OFF	Network signal not communicated

Anschluss der Geräte

Schritt1. Bitte prüfen Sie die korrekte Verbindung des Netzteils mit der Steckdose.

Schritt2. Verbinden Sie das Netzteil mit dem Switch.

Schritt3. Verbinden Sie weitere Geräte mit dem Switch unter Verwendung von Ethernet-Kabeln (z.B.: Cat.5e).

Installation physique

Indicator   100M PoE port   1000M Uplink   Function switch

Function Switch

Mark	Mode	Description
N	Standard Normal	All ports communicate freely,adapting to common data transmission environment
V	Port Isolation	Switch to VLAN mode;downlink isolating from each other,uploads and downloads data through uplink;suppress network failure like broadcast storm and virus attack
S	Super Mode	Downlink speed limitation:10M(Ultral-far transmission:250 meters)

Indicator

| Indicator		Status	Description
Power LED:P		Always ON	Normal
		Always OFF	Power Unconnected
		Flashes	Port circuit or cunrrent over-loaded
Port Isolation LED: V		Always ON	Port Isolation mode ON
Super Mode LED: S		Always ON	Super mode ON
PoE LED	Orange	Always ON	Powered equipments connected and power supply narmally
		Always OFF	No powered equipments connected or no power supply
	Green	Always ON	Network signal communicated
		Always OFF	Network signal not communicated

Branchement de l'équipement

Étape1. Inspectez soigneusement l'adaptateur
secteur et assurez-vous qu'il est correctement
connecté à une source d'alimentation.

Étape2. Branchez l'adaptateur secteur sur le switch.

Étape3. Connectez vos périphériques réseau au
switch en utilisant un câble Ethernet. (Par exemple,
Cat-5e)

Instalación física

| Indicator | 100M PoE port | 1000M Uplink | Function switch |

Function Switch

Mark	Mode	Description
N	Standard Normal	All ports communicate freely,adapting to common data transmission environment
V	Port Isolation	Switch to VLAN mode;downlink isolating from each other,uploads and downloads data through uplink;suppress network failure like broadcast storm and virus attack
S	Super Mode	Downlink speed limitation:10M(Ultral-far transmission:250 meters)

Indicator

| Indicator		Status	Description
Power LED:P		Always ON	Normal
		Always OFF	Power Unconnected
		Flashes	Port circuit or cunrrent over-loaded
Port Isolation LED: V		Always ON	Port Isolation mode ON
Super Mode LED: S		Always ON	Super mode ON
PoE LED	Orange	Always ON	Powered equipments connected and power supply narmally
		Always OFF	No powered equipments connected or no power supply
	Green	Always ON	Network signal communicated
		Always OFF	Network signal not communicated

Procedimiento de conexión del equipo

Paso1.Inspeccione el adaptador de corriente
con cuidado, y asegúrese de que está
correctamente conectado a una fuente de energía.

Paso2.Conecte el adaptador de corriente al Switch.

Paso3.Conecte sus dispositivos de red con el switch
mediante el uso de cable Ethernet.(Por ejemplo,
Cat-5e).

Fysieke installatie

Indicator   100M PoE port   1000M Uplink   Function switch

Function Switch

Mark	Mode	Description
N	Standard Normal	All ports communicate freely,adapting to common data transmission environment
V	Port Isolation	Switch to VLAN mode;downlink isolating from each other,uploads and downloads data through uplink;suppress network failure like broadcast storm and virus attack
S	Super Mode	Downlink speed limitation:10M(Ultral-far transmission:250 meters)

Indicator

| Indicator		Status	Description
Power LED:P		Always ON	Normal
		Always OFF	Power Unconnected
		Flashes	Port circuit or cunrrent over-loaded
Port Isolation LED: V		Always ON	Port Isolation mode ON
Super Mode LED: S		Always ON	Super mode ON
PoE LED	Orange	Always ON	Powered equipments connected and power supply narmally
		Always OFF	No powered equipments connected or no power supply
	Green	Always ON	Network signal communicated
		Always OFF	Network signal not communicated

Apparatuur wordt aangesloten

Stap1. Controleer het voedingsapparaat nauwkeurig en zorg er voor dat het goed op het stopcontact is aangesloten.

Stap2. Sluit het voedingsapparaat op de switch aan.

Stap3. Sluit de netwerkapparaten op de switch aan met een Ethernetkabel, bijvoorbeeld Cat 5e.

Fysisk installation

Indicator   100M PoE port   1000M Uplink   Function switch

Function Switch

Mark	Mode	Description
N	Standard Normal	All ports communicate freely,adapting to common data transmission environment
V	Port Isolation	Switch to VLAN mode;downlink isolating from each other,uploads and downloads data through uplink;suppress network failure like broadcast storm and virus attack
S	Super Mode	Downlink speed limitation:10M(Ultral-far transmission:250 meters)

Indicator

Indicator		Status	Description
Power LED:P		Always ON	Normal
		Always OFF	Power Unconnected
		Flashes	Port circuit or cunrrent over-loaded
Port Isolation LED: V		Always ON	Port Isolation mode ON
Super Mode LED: S		Always ON	Super mode ON
PoE LED	Orange	Always ON	Powered equipments connected and power supply narmally
		Always OFF	No powered equipments connected or no power supply
	Green	Always ON	Network signal communicated
		Always OFF	Network signal not communicated

Sammenkobling af udstyr

Step1. Tjek strøm adapteren omhyggeligt og sikker at
       den er forbundet til strøm kilde.

Step2. Forbind strøm adapteren med switchen.

Step3. Forbind din netværks enhed med switchen vha.
   et ethernet kabel (f.eks. Cat 5e).

Installazione fisica

Indicator   100M PoE port   1000M Uplink   Function switch

Function Switch

Mark	Mode	Description
N	Standard Normal	All ports communicate freely,adapting to common data transmission environment
V	Port Isolation	Switch to VLAN mode;downlink isolating from each other,uploads and downloads data through uplink;suppress network failure like broadcast storm and virus attack
S	Super Mode	Downlink speed limitation:10M(Ultral-far transmission:250 meters)

Indicator

Indicator		Status	Description
Power LED:P		Always ON	Normal
		Always OFF	Power Unconnected
		Flashes	Port circuit or cunrrent over-loaded
Port Isolation LED: V		Always ON	Port Isolation mode ON
Super Mode LED: S		Always ON	Super mode ON
PoE LED	Orange	Always ON	Powered equipments connected and power supply narmally
		Always OFF	No powered equipments connected or no power supply
	Green	Always ON	Network signal communicated
		Always OFF	Network signal not communicated

Equipaggiamento di connessione

Fase1.Controllare l'alimentatore con attenzione assicurarsi

che sia correttamente collegata alla sorgente elettrica.

Fase2.Collegare l'alimentatore allo switch.

Fase3.Collegare il proprio dispositivo di rete allo switch

con un cavo Ethernet (ad es. Cat.5e)

Εγκατάσταση

Indicator   100M PoE port   1000M Uplink   Function switch

Function Switch

| Mark	Mode	Description
N	Standard Normal	All ports communicate freely,adapting to common data transmission environment
V	Port Isolation	Switch to VLAN mode;downlink isolating from each other,uploads and downloads data through uplink;suppress network failure like broadcast storm and virus attack
S	Super Mode	Downlink speed limitation:10M(Ultral-far transmission:250 meters)

Indicator

Indicator		Status	Description
Power LED:P		Always ON	Normal
		Always OFF	Power Unconnected
		Flashes	Port circuit or cunrrent over-loaded
Port Isolation LED: V		Always ON	Port Isolation mode ON
Super Mode LED: S		Always ON	Super mode ON
PoE LED	Orange	Always ON	Powered equipments connected and power supply narmally
		Always OFF	No powered equipments connected or no power supply
	Green	Always ON	Network signal communicated
		Always OFF	Network signal not communicated

Συνδεδεμένος εξοπλισμός

Βήμα1. Ελέγξτε προσεκτικά τον μετασχηματιστή τροφοδοσίας και σιγουρευτείτε ότι έχει συνδεθεί σωστά στην πρίζα ρεύματος.

Βήμα2. Τοποθετήστε το τροφοδοτικό στο Switch.

Βήμα3. Συνδέστε τις δικτυακές σας συσκευές με το Switch χρησιμοποιώντας καλώδιο δικτύου (π.χ. καλώδιο κατηγορίας Cat-5e)

Instalação física

Indicator   100M PoE port   1000M Uplink Function switch

Function Switch

| Mark	Mode	Description
N	Standard Normal	All ports communicate freely,adapting to common data transmission environment
V	Port Isolation	Switch to VLAN mode;downlink isolating from each other,uploads and downloads data through uplink;suppress network failure like broadcast storm and virus attack
S	Super Mode	Downlink speed limitation:10M(Ultral-far transmission:250 meters)

Indicator

Indicator		Status	Description
Power LED:P		Always ON	Normal
		Always OFF	Power Unconnected
		Flashes	Port circuit or cunrrent over-loaded
Port Isolation LED: V		Always ON	Port Isolation mode ON
Super Mode LED: S		Always ON	Super mode ON
PoE LED	Orange	Always ON	Powered equipments connected and power supply narmally
		Always OFF	No powered equipments connected or no power supply
	Green	Always ON	Network signal communicated
		Always OFF	Network signal not communicated

Conectando Equipamento

Passo1. Verifique o adaptador de energia cuidadosamente, e assegure-se de tê-lo conectado à tomada corretamente.

Passo2. Conecte o adaptador de energia ao Switch.

Passo3. Conecte seus dispositivos de rede no Switch utilizando cabos ethernet. (ex. Cat-05e).

Inkoppling

Indicator   100M PoE port   1000M Uplink Function switch

Function Switch

| Mark	Mode	Description
N	Standard Normal	All ports communicate freely,adapting to common data transmission environment
V	Port Isolation	Switch to VLAN mode;downlink isolating from each other,uploads and downloads data through uplink;suppress network failure like broadcast storm and virus attack
S	Super Mode	Downlink speed limitation:10M(Ultral-far transmission:250 meters)

Indicator

Indicator		Status	Description
Power LED:P		Always ON	Normal
		Always OFF	Power Unconnected
		Flashes	Port circuit or cunrrent over-loaded
Port Isolation LED: V		Always ON	Port Isolation mode ON
Super Mode LED: S		Always ON	Super mode ON
PoE LED	Orange	Always ON	Powered equipments connected and power supply narmally
		Always OFF	No powered equipments connected or no power supply
	Green	Always ON	Network signal communicated
		Always OFF	Network signal not communicated

Ansluter enheter

Steg1. Kontrollera nätadaptern noga och försäkra dig
om att den är korrekt ansluten till ett eluttag.

Steg2. Anslut nätdelen till switchen.

Steg3. Anslut dina nätverksenheter med
Ethernetkabel. (ex, Kat 5e).

Diagram povezave

Indicator   100M PoE port   1000M Uplink   Function switch

Function Switch

Mark	Mode	Description
N	Standard Normal	All ports communicate freely,adapting to common data transmission environment
V	Port Isolation	Switch to VLAN mode;downlink isolating from each other,uploads and downloads data through uplink;suppress network failure like broadcast storm and virus attack
S	Super Mode	Downlink speed limitation:10M(Ultral-far transmission:250 meters)

Indicator

| Indicator		Status	Description
Power LED:P		Always ON	Normal
		Always OFF	Power Unconnected
		Flashes	Port circuit or cunrrent over-loaded
Port Isolation LED: V		Always ON	Port Isolation mode ON
Super Mode LED: S		Always ON	Super mode ON
PoE LED	Orange	Always ON	Powered equipments connected and power supply narmally
		Always OFF	No powered equipments connected or no power supply
	Green	Always ON	Network signal communicated
		Always OFF	Network signal not communicated

Povezovanje

Korak1. Preverite, če je napajalni adapter pravilno
povezan v električno omrežje.

Korak2. Priključite napajalni kabel v stikalo.

Korak3. Povežite vaše omrežne naprave z uporabo
mrežnega kabla (npr. Cat.5e).

硬體安裝

■ FGP-1031 10-Port Fast Ethernet PoE Switch, 2 x Uplink Gigabit RJ45, 8 PoE Outputs, 120W PoE Power Budget

| Indicator | 100M PoE port | 1000M Uplink | Function switch |

Function Switch

| Mark	Mode	Description
N	Standard Normal	All ports communicate freely,adapting to common data transmission environment
V	Port Isolation	Switch to VLAN mode;downlink isolating from each other,uploads and downloads data through uplink;suppress network failure like broadcast storm and virus attack
S	Super Mode	Downlink speed limitation:10M(Ultral-far transmission:250 meters)

Indicator

Indicator		Status	Description
Power LED:P		Always ON	Normal
		Always OFF	Power Unconnected
		Flashes	Port circuit or cunrrent over-loaded
Port Isolation LED: V		Always ON	Port Isolation mode ON
Super Mode LED: S		Always ON	Super mode ON
PoE LED	Orange	Always ON	Powered equipments connected and power supply narmally
		Always OFF	No powered equipments connected or no power supply
	Green	Always ON	Network signal communicated
		Always OFF	Network signal not communicated

連結網路裝置

步驟1. 請仔細檢察並確認電源供應器已連接上電源插座.

步驟2. 請將電源供應器連接上此交換機.

步驟3. 請使用乙太網路線(例如: Cat-5e 線)連接交換機與其他網路設備

Физическая установка

Function Switch

| Mark	Mode	Description
N	Standard Normal	All ports communicate freely,adapting to common data transmission environment
V	Port Isolation	Switch to VLAN mode;downlink isolating from each other,uploads and downloads data through uplink;suppress network failure like broadcast storm and virus attack
S	Super Mode	Downlink speed limitation:10M(Ultral-far transmission:250 meters)

Indicator

Indicator		Status	Description
Power LED:P		Always ON	Normal
		Always OFF	Power Unconnected
		Flashes	Port circuit or cunrrent over-loaded
Port Isolation LED: V		Always ON	Port Isolation mode ON
Super Mode LED: S		Always ON	Super mode ON
PoE LED	Orange	Always ON	Powered equipments connected and power supply narmally
		Always OFF	No powered equipments connected or no power supply
	Green	Always ON	Network signal communicated
		Always OFF	Network signal not communicated

Подключение оборудования

Шаг1. Внимательно осмотрите блок питания и надлежащим образом подключите его к источнику питания.

Шаг2. Подключите блок питания к коммутатору.

Шаг3. Подключите сетевые устройства к коммутатору посредством Ethernet кабеля (например, категории 5е)

Fizyczna instalacja

Indicator   100M PoE port   1000M Uplink   Function switch

Function Switch

Mark	Mode	Description
N	Standard Normal	All ports communicate freely,adapting to common data transmission environment
V	Port Isolation	Switch to VLAN mode;downlink isolating from each other,uploads and downloads data through uplink;suppress network failure like broadcast storm and virus attack
S	Super Mode	Downlink speed limitation:10M(Ultral-far transmission:250 meters)

Indicator

Indicator		Status	Description
Power LED:P		Always ON	Normal
		Always OFF	Power Unconnected
		Flashes	Port circuit or cunrrent over-loaded
Port Isolation LED: V		Always ON	Port Isolation mode ON
Super Mode LED: S		Always ON	Super mode ON
PoE LED	Orange	Always ON	Powered equipments connected and power supply narmally
		Always OFF	No powered equipments connected or no power supply
	Green	Always ON	Network signal communicated
		Always OFF	Network signal not communicated

Podłączenie urządzenia

Punkt1. Sprawdź dokładnie zasilacz i upewnij się czy jest prawidłowo podłączony.

Punkt2. Podłączenie zasilacz do switcha.

Punkt3. Podłącz swoje urządzenie sieciowe do switcha poprzez kabel typu Ethernet, kategori 5e.